

Home / Air conditioning / Air conditioners / LG CAPACITOR, $6/40\mu F$



Image coming soon



LG CAPACITOR, 6/40µF

Part Number: 2A00986E

This is a 2A00986E LG CAPACITOR, $6/40\mu F$ replacement Capacitor / Fuse for LG Airconditioners. Statewide Appliance Spares can supply you with a range of appliance spare parts to suit your LG Airconditioner.

Ensure your appliance is working at its best with a replacement 2A00986E LG CAPACITOR, $6/40\mu F$ from Statewide Appliance Spares. We offer competitive pricing and fast, Australia wide delivery to make buying spare parts easier.

Product: LG CAPACITOR, 6/40µF

Part: 2A00986E Brand: LG

Replacement: Capacitor / Fuse for Airconditioners

Product Description

Models This Part Suits

6+40UF 370V 50/60HZ 50MM 135MM SEAM 4-3-2 250

0.0 ****
No rating available

A message to our customers COVID-19 update Free Call 1800 005 220 Statewide Appliance Spares Frouucts My account Commercial equipment range Free call | 1800 005 220 105 Sir Donald Bradman Drive, Hilton, SA 5033 Privacy Policy | Conditions of Use SECURE SSLENCRYPTION Free Call 1800 005 220 Conditions of Use

0.0 ******
No rating available